	# a b c d e f g h	Always make sure the opera Staring at the opera Disassemble/dism Unscrew 3 screws [Take out terminal b Remove wires of the Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	17] and remove base lock [20] from base [6	ed from th cause eye [6] 6] rom termina	e power supply	Tools needed CROSSHEAD SCREWDRIVER			
	# a b c d e f g h	<u>Marnings</u> Always make sure th Always make sure th Staring at the opera Unscrew 3 screws [Take out terminal b Remove wires of the Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	ne DC cable is detach ting light source may antle steps 17] and remove base lock [20] from base [6 control gear - psu [4] fr vire [1] from terminal	ed from th cause eye [6] 6] rom termina	e power supply				
	# a b c d e f g h	Always make sure the Always make sure the Staring at the operation Disassemble/dism Unscrew 3 screws [Take out terminal be Remove wires of the Remove earthing we Unscrew 2 screws [Unscrew 1 screw [1]	ne DC cable is detach ting light source may antle steps 17] and remove base lock [20] from base [6 control gear - psu [4] fr vire [1] from terminal	ed from th cause eye [6] 6] rom termina	e power supply		2) R PH		6
	a b c d e f g h	Unscrew 3 screws [Take out terminal b Remove wires of the Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	17] and remove base lock [20] from base [6 control gear - psu [4] fr vire [1] from terminal	6] rom termina			R PH		
	b c d e f g h	Take out terminal b Remove wires of the Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	lock [20] from base [6 control gear - psu [4] fr vire [1] from terminal	6] rom termina		CROSSHEAD SCREWDRIVER	R PH		
(((c d e f g h	Remove wires of the Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	control gear - psu [4] fr vire [1] from terminal	rom termina					
e f	d e f g h	Remove earthing w Unscrew 2 screws [Unscrew 1 screw [1	vire [1] from terminal			-			
	e f g h	Unscrew 2 screws [Unscrew 1 screw [1			al block [20] by unscrewing	FLATHEAD SCREWDRIVE			
	f g h	Unscrew 1 screw [1	13] and remove 2 pul			FLATHEAD SCREWDRIVE			
	g h					TORXHEAD SCREW DRIVER			
Þ	h		-	-	with wire and washer [2]	TORXHEAD SCREW DRIVER	<u>120</u>		
			iffuser [5] and unsnap			-			
	1 I				insulation [11] and washers [14]	TORXHEAD SCREW DRIVER	<u>(T10</u>		
		Remove gasket [9]		m light sou	urce-led module [14]	WAGO TOOL #2060	_	~ ~	
	# 1 2	COMPONENT RING TONGUE WI TOOTH WASHER	TH EARTHING WIRE	QTY 1	SKU Color 915005841701 black	Country			·• · · · · · · · · · · · · · · · · · ·
	3	PULL RELIEF		1					
ŀ	4	PULL RELIEF		1					
	5	DIFFUSER		1					
	6	BASE		1					
	7	CONTROL GEAR -	PSU	1					
⊢	8	BASE		1					
┡	9	GASKET		1					
		LIGHT SOURCE - L	ED MODULE	1					U I
		INSULATION		1					
ŀ	_	SCREW		5					
L_	_	SCREW		2					
_	_	WASHER		3					
-		SCREW		1					
	·	TERMINAL BLOCK SCREWS		2					
	1/	JUKEVVS		2				STATUS	DESCRIPTION
									Nyro Hue
								NAME Ku Pa	
								CHECKED	

